



BLUE RIDGE RACE LAB, LLC

— Fuel, Oil & Tire Analysis —

January 18, 2022
Mr. Davey Sammons
Indoor Auto Racing

Subject: Race Tire scans on samples submitted on January 15, 2022 Indoor Auto Racing. Blue Ridge Race Lab LLC received two samples for Race Tire scans on tire samples identified by evidence bag number/date code and type of tire. The samples were received in good condition in sealed evidence bags.

Summary of Race Tire Analysis:

BRRL LSID	Customer ID	Tire ID	Results
22-0003	1354469/EY82	Hoosier H1N4	Does not conform to the benchmark
22-0003Dup	1354469/EY82	Hoosier H1N4	Does not conform to the benchmark
22-0004	1354476/8F6T	Hoosier H1N4	Conforms to the benchmark

The sample LSID-22-0003 1354469/EY82 Hoosier H1N4 was found to not conform to the manufacturer submitted benchmark and was analyzed in duplicate to confirm the original scan result, which is our laboratory protocol. The duplicate result confirmed the original result, that this sample does not conform to the manufacturer submitted benchmark sample. I contacted the manufacturer with the date code of this sample and was advised to use Hoosier H1N4 1293676 as the benchmark for this sample. I have analyzed this benchmark sample and enclosed the tire scan of Hoosier H1N4 1293676 for comparison with the non-conforming tire sample. I appreciate the opportunity to provide tire analysis for your speedway.

Sincerely,



Kim Johnson
Blue Ridge Labs, Inc.